

**DS-30 / DS-50 Fly Away Service Kit**  
**Part Number for kit = FAS-KDS-313, FAS-KDS-323, FAS-KDS-333**

**Case 1 of 3 part number FAS-KDS-313**

Check Upon Receipt	Part Number	Description	Quantity	Price
	002-885-200	66P3311 MIF pcb	1	TBA
	002-885-210	66P3312 MFT pcb	1	TBA
	002-885-230	66P3319 MLG pcb	1	TBA
	002-886-160	66P3610A VPR pcb	1	TBA
	002-886-170	66P3610B VPR pcb	1	TBA
	002-886-180	66P3400A STXB pcb	2	TBA
	002-888-140	66P3310A MCP pcb	1	TBA

**Case 2 of 3 part number FAS-KDS-323**

Check Upon Receipt	Part Number	Description	Quantity	Price
	000-128-877X	HOFG-1H (V 3.1) Rate of Turn Gyro	1	\$27,275.00
	002-882-700	Go To 002-891-190		NLA
	002-891-190	66P3333 NPR pcb	1	\$1,995.00
	002-291-200	66P3335 NPW2 pcb	1	TBA
	002-883-860	66P3331A NTXA pcb	1	TBA
	002-891-790	66P3331B NTXB pcb	1	TBA
	002-891-450	66P3615 VIF pcb	1	TBA
	000-128-968	LCD Backlights	16	\$85.00

**Case 3 of 3 part number FAS-KDS-333**

Check Upon Receipt	Part Number	Description	Quantity	Price
	002-885-740	66P3602B VSW1 pcb	1	TBA
	002-885-770	66P33602A VSW1 pcb	1	TBA
	002-885-800	66P3600 VLE pcb	1	TBA
	002-885-810	66P3601 VCP pcb	1	TBA
	002-885-890	66P3603 VPW pcb	1	TBA
	002-885-960	66P3335A NPW2A pcb	1	TBA
	002-886-200	66P3612 VOC pcb	1	TBA
	002-886-210	66P3613 VAE pcb	1	TBA
	002-886-220	66P3614 VDE pcb	1	TBA
	002-886-230	66P3616A MCNA	1	TBA
	002-885-910	DS-510/511 Power Supply Assembly	1	TBA
	002-885-940	DS-5 10-A Power Module	1	TBA

NOTE: PLEASE COMPLETE AN INVENTORY OF THIS KIT IMMEDIATELY UPON RECEIPT AND REPORT ANY DISCREPANCIES. FAILURE TO DO SO WILL RESULT IN YOUR COMPANY BEING BILLED APPROPRIATE TESTING AND/OR REPLACEMENT COSTS FOR ANY MISSING/UNSEALED/DAMAGED MATERIALS UPON RETURN OF THIS KIT. PLEASE REPACK PROPERLY.