



PACKING LIST FOR FAR2157BB

| Box 1 - RPU013/50 | | WT: 29 Lbs DIM: 19"W x 21"L x 12"H | |
|-------------------|-------------|------------------------------------|---|
| 1 | RPU013 | Processor Unit (set for 50KW) | 1 |
| 2 | 000-155-826 | Fuse FGBO 10A | 4 |
| 3 | | Fuse | |
| 4 | | Fuse | |
| 5 | 000-147-417 | Wago Tool (small) | 1 |
| 6 | 000-808-981 | Wago Tool (large) | 1 |
| 7 | 000-538-118 | Crimp Lug FV2-4 | 2 |
| 8 | | <i>alternate to above</i> | |
| 9 | | <i>alternate to above</i> | |
| 10 | | <i>alternate to above</i> | |
| 11 | OME-352-21Z | Operator's Manual | 1 |
| 12 | OSE-351-90Z | Operator's Guide | 1 |
| 13 | IME-352-21Z | Installation Manual | 1 |

| Box 2 - Control Unit | | WT: 10 Lbs DIM: 11"W x 19"L x 8"H | |
|----------------------|--------------------|-----------------------------------|---|
| <u>Part No.</u> | <u>Description</u> | <u>Quantity</u> | |
| 1 | RCU014 | Control Unit w/ Cable Assembly | 1 |
| 2 | 100-306-251 | Fixing Bracket | 1 |
| 3 | 000-147-167 | Grommet "G39" | 1 |
| 4 | 000-803-043 | "3M" Brand Bumper Cushion | 3 |
| 5 | 000-881-447 | Washer Head Screw M4 x 12 | 2 |
| 6 | 000-881-447 | Washer Head Screw M4 x 12 | 4 |

| Box 3 - Gearbox | | WT: 155 Lbs DIM: 25" W x 30"L x 27"H | |
|-----------------|--------------------|--------------------------------------|---|
| <u>Part No.</u> | <u>Description</u> | <u>Quantity</u> | |
| 1 | RSB106 | 50KW Xband Gearbox w/ RTR083 | 1 |
| 2 | 300-130-020 | Seal Washer | 4 |
| 3 | 100-091-112 | Corrosion Proof Rubber Mat | 2 |
| 4 | 000-808-981 | Wago Tool (large) | 1 |
| 5 | 000-538-118 | Crimp Lug FV2-4 | 6 |
| 6 | 000-538-123 | Crimp Lug FV5.5-4 | 1 |
| 7 | 000-864-263 | Spring Washer M12 | 4 |
| 8 | 000-864-132 | Flat Washer M12 | 4 |
| 9 | 000-163-112 | Hex Nut M12 | 4 |
| 10 | 000-862-191 | Hex Bolt M12x60 | 4 |
| 11 | 000-158-856 | Hex Nut M6 | 1 |
| 12 | 000-158-855 | Spring Washer M6 | 1 |
| 13 | 000-158-854 | Flat Washer M6 | 3 |
| 14 | 000-862-180 | Hex Bolt M6x25 | 1 |
| 15 | 000-566-000 | Grounding Wire .3M | 1 |

| For Internal Use Only | |
|-----------------------|----------------|
| Serial No. 4318 - | |
| Checked By: | |
| Tech | _____ |
| Date | _____ |
| RPU013/50 | |
| | |
| | sub SP03-14404 |
| | sub SP03-14405 |
| | sub SP06-14406 |
| | sub CP03-25602 |
| | " |
| | " |
| | sub CP03-25603 |
| | " |
| | " |
| | |
| | |
| | |
| | |

| RCU-014 | |
|------------|-----------------|
| <u>Yes</u> | <u>Remarks</u> |
| | |
| | sub 008-535-610 |
| | " |
| | " |
| | |
| | sub CP03-025604 |

| RSB106 | |
|------------|----------------|
| <u>Yes</u> | <u>Remarks</u> |
| | |
| | sub CP03-31301 |
| | " |
| | " |
| | " |
| | " |
| | " |
| | " |
| | " |
| | " |
| | " |
| | " |
| | " |
| | " |
| | " |



PACKING LIST FOR FAR2157BB (con't)

| For Internal Use Only | |
|-----------------------|-------|
| Serial No. 4318 - | |
| Checked By: | |
| Tech | _____ |
| Date | _____ |

Box 4 - Cable **WT: 85 Lbs DIM: 23"W x 23"L x 7"H**

| | <u>Part No.</u> | <u>Description</u> | <u>Quantity</u> |
|---|-----------------|-------------------------|-----------------|
| 1 | 000-147-373 | Cable 50M (Type RW9600) | 1 |

| 000-147-373 | |
|-------------|----------------|
| <u>Yes</u> | <u>Remarks</u> |
| | |

Box 6 - PSU006-106AC-60 **WT: 15 Lbs DIM: 17"W x 22"L x 9"H**

| | <u>Part No.</u> | <u>Description</u> | <u>Quantity</u> |
|---|-----------------|----------------------------|-----------------|
| 1 | PSU006 | Power Control Unit | 1 |
| 2 | 000-155-840 | Fuse FGBO 5A (for DC) | 2 |
| 3 | | Fuse for Alternative Input | 2 |
| 4 | 000-538-118 | Crimp Lug FV2-4 | 14 |

| PSU006-106AC-60 | |
|-----------------|----------------|
| <u>Yes</u> | <u>Remarks</u> |
| | |
| | sub SP03-15501 |
| | sub SP03-15502 |
| | |