

# FURUNO

## PACKING LIST FOR FI70BW

For Internal Use Only	
Serial No. _____	
Checked By: _____	
Tech _____	
Date _____	
FI70	
Yes	Remarks
	CP26-02001
	"
	"
	"
	"

**Box 1 - FI70** **Wt: 2.5 lbs. Dim: 16" x 8" x 3"**

	<u>Part No.</u>	<u>Description</u>	<u>Quantity</u>
1	FI70	Color Display	1
2	001-105-770-10	NMEA2K Cbl Assy 6m	1
3	100-394-750-10	Flush Mount Sponge	1
4	000-167-453-10	Flat Washer M3	2
5	000-167-404-10	Spring Washer M3	2
6	000-167-826-10	Wing Nut	2
7	000-167-804-10	Threaded Rod M3x40	2
8	E72-014-03Z	User Handbook	1
9	C72-014-02Z	Flush Mount Template	1
10	MDC-728-10Z	Environmental Data Sheet	1

FI5001/30M	
Yes	Remarks

**Box 2 - FI5001/30M** **Wt: 5 lbs. Dim: 16"x10"x7"**

	<u>Part No.</u>	<u>Description</u>	<u>Quantity</u>
1	FI5001	Wind Vane Assy, 2 pieces	1
2	IMC-726-61Z	Installation Manual (bilingual)	1
3	000-158-850	4x20 Self Tapping Screw	4
4	000-010-511	30M Wind Inst Cable Assy	1

FI5002	
Yes	Remarks

**Box 3 - FI5002** **Wt: 1.2 lbs. Dim: 9.5" x 7" x 2.5"**

	<u>Part No.</u>	<u>Description</u>	<u>Quantity</u>
1	000-011-748	J-Box 220x84x52mm	1
2	000-158-850	Self Tapping Screw 4x20	4
3	000-167-891	Wire Tie (100mm)	9
4	000-166-944	Power Cable 2m	1
5	C72-007-02Z	Installation Instructions	1

IF-NMEAFI	
Yes	Remarks

**Box 4 - IF-NMEAFI** **Wt: 1 lb. Dim: 11" x 8" x 2"**

	<u>Part No.</u>	<u>Description</u>	<u>Quantity</u>
1	IF-NMEAFI	Analog NMEA Data Converter	1
2	000-167-940-10	Tapping Screw 3x20	2
3	C72-014-04Z	Installation Guide	1