

# FURUNO

## PACKING LIST FOR DRS12AX

For Internal Use Only	
Serial No. _____	
Checked By: _____	
Tech _____	
Date _____	
RSB134-113	
Yes	Remarks
	SP03-18301
	CP03-37101
	"
	"
	"
	"

**Box 1 - RSB134-113** **Wt: 41 lbs. Dim: 20" x 18" x 16"**

	<u>Part No.</u>	<u>Description</u>	<u>Quantity</u>
1	RSB134-113	Scanner Unit	1
2	000-192-660-10	Fuse ATV10A60V	1
3	100-403-040-10	Corrosion-proof pad	4
4	000-167-491-10	Hex Nut M12	8
5	000-167-397-10	Spring Washer M12	4
6	000-167-417-10	Flat Washer M12	4
7	000-191-051-10	Hex Stud M12x70	4
8	IME-364-60Z	Installation Manual	1
9	C32-007-03Z	Mounting Template	1
10	MDC-364-60Z	Environmental Data Sheet	1

**Box 2 - 001-512-620-00** **Wt: 9 lbs. Dim: 12" x 12" x 6"**

	<u>Part No.</u>	<u>Description</u>	<u>Quantity</u>
1	001-512-620-00	Signal/Power Cable Assy 15M	1
2	000-194-913-10	Fuse 5A	1
3	000-192-660-10	Fuse 10A	1
4	000-193-055-10	Fuse 15A	1
5	C32-018-01Z	Fuse Change Notice	1

001-512-620-00	
Yes	Remarks