



PACKING LIST FOR PSU012

Box 1 - PSU012 **Wt: 9 lbs. Dim: 16"x14"x10"**

	<u><i>Part No.</i></u>	<u><i>Description</i></u>	<u><i>Quantity</i></u>
1	PSU012	Power Supply NN3D 4A-12A	1
2	000-157-874	15A fuse	2
3	000-155-839	10A fuse (or sub 000-155-826)	2
4	001-167-890-10	5M Cable Assy RJ45	1
5	000-152-217	5M Power Cable Assy	1
6	000-158-850	4 x 20 Tapping Screw	4
7	001-183-760-00	XH Connector Assy	1
8	C32-007-06Z	Notice for Fuse Replacement	1

<i>For Internal Use Only</i>	
Serial No. _____	
Checked By: _____	
Tech _____	
Date _____	
PSU012	
<u>Yes</u>	<u>Remarks</u>
	CP03-32700
	"
	CP03-32701
	"